

# 80/215/RVC

## **RESULT OF VOTING ON CDV**

Project number:	Reference number of the CD
80/61097-10	80/177/CDV
IEC/TC or SC	Date of circulation
80	1998-12-11

Title of the TC or SC concerned

Maritime navigation and radiocommunication equipment and systems

Title of the committee draft: IEC 61097 - Maritime navigation and radiocommunication equipment and systems - Global maritime distress and safety system (GMDSS) - Part 10: Inmarsat-B Ship earth station equipment - Operational and performance requirements - methods of testing and required test results						
The above-mentioned document was circulated to National Committees with a request that voting take place for approval for circulation as an FDIS (or publication as a Technical Report)						
Voting results						
see printout attached						
Comments received – see annex						
In the case that the approval criteria for acceptance have been m						
a The committee draft for vote (CDV) will be registered as an	FDIS by (date) 1998-12					
<b>DECISION OF THE CHAIRMAN</b> (in cooperation with the secretariat), i orin the case of a draft Technical Report	n the case that the approval criteria for acceptance have not been met					
b The committee draft for vote (CDV) will be published as a T	echnical Report by (date)					
c A revised committee draft will be circulated as a committee	draft for vote (CDV) by (date)					
d A revised committee draft will be circulated for comment by (date)						
e The committee draft and comments will be discussed at the next meeting (date)						
NOTE — In the case of a proposal <i>b</i> , <i>c</i> or <i>d</i> made by the chairman, P-members objecting to such a proposal shall inform the Central Office with copy to the secretary in writing within 2 months of the circulation of this compilation (see 2.6.5 of Part 1 of the ISO/IEC Directives).						
Name and signature of the Secretary  Name and signature of the Chairman						
Mr. Peter F.C. GRIFFITHS	Dr. A.P. NORRIS					

#### Result of Voting on CDV - Document 80/177

IEC 61097-10: Maritime navigation and radiocommunication equipment and systems - Global maritime distress and safety system (GMDSS) - Part 10: Inmarsat-B Ship earth station equipment - Operational and performance requirements, methods of testing and required test results

Circulation Date: 1998-04-03 Closing Date: 1998-09-15
---

Country	Status	Vote	Sent	Received	Comments
Belgium	P	Y	98-08-24	98-08-28	
China	P	Y	98-08-17	98-08-17	
Denmark	P	Y	98-09-07	98-09-07	Y
France	P	Y	98-09-14	98-09-14	
Germany	P	Y	98-08-28	98-08-28	
Ireland	0	Y	98-09-15	98-09-15	
Italy	P	Y	98-07-30	98-07-30	
Japan	P	Y	98-08-26	98-08-26	Y
Netherlands	P	Y	98-09-01	98-09-01	
Norway	P	Y	98-09-04	98-09-07	
Portugal	_	A	98-09-03	98-09-03	
Russian Fed.	P	Y	98-05-26	98-06-17	Y
Sweden	P	Y	98-09-11	98-09-11	
U.S.A.	P	Y	98-09-15	98-09-15	
United Kingdom	P	Y	98-08-25	98-08-25	

		Approval	Result
		Criteria	
P-members voting: 13	P-members in favour: 13 = 100 %	>= 67%	APPROVED
Total votes cast: 14	Total against : 0 = 0 %	<= 25%	APPROVED

| Final Decision: APPROVED|

Provisional status on 1998-12-02

#### NOTES

- 1 Vote: Does the National Committee agree to the circulation of the draft as a FDIS: Y = In favour; N = Against; A = Abstention.
- 2 Only votes received before the closing date are counted in determining the decision. Late Votes: (0).
- 3 Abstentions are not taken into account when totalizing the votes.
- 4 P-members not voting: Egypt; Romania; (2).

Document

### Annex

Date

				19	98-11-24		80/177/CDV		
National Committee	Clause/ Subclause	Paragraph Figure/ Table	Type of comment (General/ Technical/ Editorial)	COMMENTS  Comments shall be reproduced as received, either by re-typing them, or by pasting them directly on this form			OBSERVATIONS OF THE SECRETARIAT on each comment submitted		
Japan	1		Editorial	The sentence should read as - "All text of this standard, whose wording is identical to that in the IMO SOLAS Convention 1974 as amended and IMO Resolution A.808 is printed in <i>italics</i> , and it is followed by the resolution or recommendation and paragraph number indicated between brackets."			Agreed.		
Japan	2		Editorial	The edition number should be added after 60945.		Not agreed. The year defines it.			
Japan	2		Editorial	IMO SOLAS should be expressed as - "IMO International Convention Safety of Life at Sea (SOLAS) 1974, as amended	for the	Agreed.			
Japan	3		Editorial	Formal spelling should be used - Organization for IMO, and Organization Standardization for ISO.	ition and	Agreed.			
Denmark	4.3.7		Technical	The IMO Subcommittee on Radiocommunications,, Search and Rescu its 3 <sup>rd</sup> session February 1998 specific clarifications on protection of the button, especially that the distress button should be protected by a spilid or cover.  It is recommended to include this text in subclause 4.3.7. The text is rebelow. However, it is primarily the clauses 1.3 (protection) and 1.4 (at independent actions) which are relevant concerning this particular doc MSC CIRCULAR 862  Clarifications of certain requirements in IMO performance standards for GMI  1. The Maritime Safety Committee, at its sixty-ninth session 11 to 20 May 1998, a following clarifications of certain requirements in IMO performance standards for equipment, developed by the Sub-Committee on Radiocommunications and Se Rescue (COMSAR), at its third session (23 to 27 February 1998), with a view to number of false distress alerts, and was of the opinion that such clarifications of Member Governments in deciding whether equipment installed on or after 1 Fe meets these requirements.  1. "DEDICATED DISTRESS BUTTON"  This button should not be any of an ITU-T input panel or an ISO keyboard association.  This button should be a single button for no other purpose than to initiate a distribution should be a single button for no other purpose than to initiate a distribution.  This button should be a single button for no other purpose than to initiate a distribution should be red in colour and marked "DISTRESS".  2. "CLEARLY IDENTIFIED"  The distress button should also be marked "DISTRESS".  3. "PROTECTED AGAINST INADVERTENT ACTIVATION"  The required protection of the distress button should consist of a spring loaded permanently attached to the equipment by e.g. hinges. It should not be necessary for the use additional	e distress bring loaded reproduced t least two cument.  IDSS equipment approved the for GMDSS earch and to reduce the would assist ebruary 1999  ociated with the ed for normal ress alert.  a non-	has been not part of Resolution Government Relevant publications and reference The MSC normative Included a In	parts have been included in es 4.3.5 to 4.3.7 - not in italics enced to the MSC Circular.  Circular has been included in the references.		

Document

Date

					1998-11-24		80/177/CDV
National Committee	Clause/ Subclause	Paragraph Figure/ Table	Type of comment (General/ Technical/ Editorial)	COMMENTS  Comments shall be reproduced as received, either by re-typing them, or by p  on this form	COMMENTS reproduced as received, either by re-typing them, or by pasting them directly		TIONS OF THE SECRETARIAT mment submitted
				seals or to break the lid or cover in order to operate the distress button. The operation of the distress button should generate a visible and audible i distress button should be kept pressed for at least 3 seconds. A flashing light and an intersignal should start immediately. After the 3 seconds the transmission of the distress alert indication should become steady.  4 "AT LEAST TWO INDEPENDENT ACTIONS" Lifting of the protective lid or cover is considered the first action. Pressing the asspecified above is considered as the second independent action.  5 "INTERRUPTING THE DISTRESS ALERT AT ANY TIME" It should be possible to interrupt repetitive transmissions of distress messal should not interrupt the transmission of a distress alert or distress message in progress prevent repetitive transmissions of a distress message.  2. Member Governments are invited to bring the above clarifications to the atternant of the statemanufacturers, shipowners, seafarers and all others concerned.	mittent acoustic is initiated and the he distress button ges. Such operation as but should	there are	at 4.3.7  ded at 4.3.4. In INMARSAT-B  no repetitive transmissions of the rare calls not alerts.

4